

## ATTACHMENT - DEVIATIONS

---

## Deviations

§60.5420(b)(2-4)(ii); (5-6)(iii) and §60.5420a(b)(2-4)(ii); (5-6)(iii)

| Facility  | Equipment Name   | Explanation  |
|---|--|--|
| Three (3) Well Pads as follows:<br>MOR30, RHL23, RHL4 | 23 Pneumatic<br>Controllers<br>(see Pneumatic<br>Controller Affected<br>Facilities list) | §60.5420a(b)(5)(iii) Deviations:<br>Continuous bleed controllers > 6 scfh were installed accidentally by contractor without<br>CNX knowledge. Controllers exceeded the bleed rate limitation and were not tagged.<br>Replaced with low bleed kits. |
|   |  |  |
|   |  |  |
|   |  |  |
|   |  |  |
|   |  |  |
|   |  |  |
|   |  |  |
|   |  |  |

1. LDAR deviations noted on the LDAR Summary Table.